


**METHOD OF DRAWING CERTIFICATION MARK AND REGISTRATION NUMBER**

This drawing is regulated according to the 'Regulations Governing Commodity Inspection Mark.' Drawing Method of the Product Safety Mark:



- (a) There is no size restriction on the Mark, but the Mark shall be affixed to the body of the product in appropriate proportion (please see mark in grid).
- (b) The obligatory inspection applicant shall use non-degenerate materials to print/ produce the certification mark (the Product Safety Mark and the identification number), which shall be affixed to each product in a visible, legible, indelible and immovable manner.
- (c) The affixing of other markings on the product, which are likely to mislead or confuse the consumers or the third parties, shall be prohibited.
- (d) The Certification Mark must be affixed to the body of the product. However, if the product is too small to accommodate the Mark, the Certification Mark shall be affixed in accordance with the following ways.
  - If the product has its packaging, it shall be affixed to its smallest package.
  - If the product has no packaging or it is not appropriate to affix the Mark on the packaging, it may be attached to the product by hang tags.
  - If the ways of affixing to the packaging and hang tags are not appropriate, it shall be put inside the packaging.
  - Other ways approved by the BSMI.

The Certification Mark should be affixed at a conspicuous location on the product in order for the consumers to identify it when they buy and/or use the product.

Examples of Certification Mark are shown as follows.

